



National Transportation Safety Board Aviation Accident Final Report

Location:	CARTERSVILLE, GA	Accident Number:	ATL89FA171
Date & Time:	06/29/1989, 0004 EDT	Registration:	N125CA
Aircraft:	DASSAULT-BREGUET FALCON 20	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	2 Fatal
Flight Conducted Under:	Part 91: General Aviation - Positioning		

Analysis

THE CREW ARRIVED AT THE ARPT ABOUT 20 MIN BEFORE THE PLANNED MIDNIGHT TAKEOFF TIME, AFTER THE PLT-IN-COMMAND HAD SPENT THE DAY MOVING FURNITURE. A NGT WATCHMAN NOTED THAT THE PREFLT INSPN & TAKEOFF ROLL TO ROTATION/LIFT-OFF WAS NORMAL. THERE WAS NO POST-TAKEOFF RADIO CALL TO EITHER UNICOM OR ATC, ALTHOUGH THE CREW HAD FILED AN IFR FLT PLAN. AFTER TAKING OFF FROM RWY 36, THE ACFT CRASHED ABOUT 1.8 MI NORTH OF THE RWY. THE WRECKAGE WAS FOUND AFTER INTERRUPTION OF ELECTRICAL POWER TO A NEARBY CITY. INITIAL IMPACT WAS WITH TREES, WHILE IN A SHALLOW/LEFT/DESCENDING TURN. AN AREA OF TREES ABOUT 1/2 MI LONG WAS DAMAGED BY IMPACT & FIRE. BEFORE COMING TO REST, THE ACFT HIT A POWERLINE SUPPORT TOWER. THERE WAS EVIDENCE THE ACFT WAS TRAVELING AT ABOUT 260 KTS, WHEN IT CRASHED. NO PREIMPACT PART FAILURE OR MALFUNCTION WAS FOUND THAT WOULD HAVE RESULTED IN THE ACDNT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FAILURE OF THE PILOT-IN-COMMAND (PIC) TO ASSURE THAT THE AIRCRAFT MAINTAINED A CLIMB PROFILE AFTER TAKEOFF. FACTORS RELATED TO THE ACCIDENT WERE: DARK NIGHT, THE CREW'S LACK OF VISUAL PERCEPTION AT NIGHT, THE PIC'S LACK OF REST (FATIGUE), AND THE COPILOT'S FAILURE TO ATTAIN REMEDIAL ACTION.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT
Phase of Operation: TAKEOFF

Findings

1. (F) LIGHT CONDITION - DARK NIGHT
2. (C) CLIMB - NOT MAINTAINED - PILOT IN COMMAND
3. (F) VISUAL/AURAL PERCEPTION - PILOT IN COMMAND
4. (F) FATIGUE(LACK OF SLEEP) - PILOT IN COMMAND
5. (F) REMEDIAL ACTION - NOT ATTAINED - COPILOT/SECOND PILOT
6. (F) VISUAL/AURAL PERCEPTION - COPILOT/SECOND PILOT
7. OBJECT - TREE(S)
8. OBJECT - ELECTRICAL TOWER

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: TAKEOFF

Factual Information

Pilot Information

Certificate:	Airline Transport	Age:	38, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane; Helicopter	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 1 Valid Medical--no waivers/lim.	Last Medical Exam:	02/14/1989
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	7940 hours (Total, all aircraft), 770 hours (Total, this make and model), 5820 hours (Pilot In Command, all aircraft), 196 hours (Last 90 days, all aircraft), 45 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Manufacturer:	DASSAULT-BREGUET	Registration:	N125CA
Model/Series:	FALCON 20 FALCON 20	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Transport	Serial Number:	208
Landing Gear Type:	Retractable - Tricycle	Seats:	2
Date/Type of Last Inspection:	04/01/1989, AAIP	Certified Max Gross Wt.:	28660 lbs
Time Since Last Inspection:	164 Hours	Engines:	2 Turbo Fan
Airframe Total Time:	13547 Hours	Engine Manufacturer:	GE
ELT:	Not installed	Engine Model/Series:	CF700-2D2
Registered Owner:	PHOENIX AIR GROUP, INC.	Rated Power:	4500 lbs
Operator:	PHOENIX AIR GROUP, INC.	Air Carrier Operating Certificate:	On-demand Air Taxi (135)
Operator Does Business As:		Operator Designator Code:	PHXA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Night/Dark
Observation Facility, Elevation:	FTY, 841 ft msl	Observation Time:	2350 EDT
Distance from Accident Site:	20 Nautical Miles	Direction from Accident Site:	130°
Lowest Cloud Condition:	Unknown / 0 ft agl	Temperature/Dew Point:	22° C / 22° C
Lowest Ceiling:	Broken / 8000 ft agl	Visibility	2 Miles
Wind Speed/Gusts, Direction:	4 knots, 240°	Visibility (RVR):	0 ft
Altimeter Setting:	30 inches Hg	Visibility (RVV):	0 Miles
Precipitation and Obscuration:			
Departure Point:	(6A0)	Type of Flight Plan Filed:	IFR
Destination:	MONTGOMERY, AL (MGM)	Type of Clearance:	None
Departure Time:	0004 EDT	Type of Airspace:	Class G

Airport Information

Airport:	CARTERSVILLE (6A0)	Runway Surface Type:	Asphalt
Airport Elevation:	753 ft	Runway Surface Condition:	Dry
Runway Used:	36	IFR Approach:	None
Runway Length/Width:	5000 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	N/A	Aircraft Fire:	On-Ground
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Fatal	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	PRESTON E HICKS	Adopted Date:	06/28/1991
Additional Participating Persons:	ROFF SASSER; ATLANTA, GA WILLIAM H THOMPSON; CINCINNATI, OH CHARLES CUTFIELD; CINCINNATI, OH MARC VALLE; TETERBORO, NJ		
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.