



# National Transportation Safety Board Aviation Accident Final Report

<b>Location:</b>	POINT LAY, AK	<b>Accident Number:</b>	ANC94LA009
<b>Date &amp; Time:</b>	10/08/1993, 1735 AKD	<b>Registration:</b>	N811E
<b>Aircraft:</b>	DOUGLAS C-54GDC	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	3 None
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Business		

## Analysis

THE CAPTAIN STATED THERE WERE NO RUNWAY CONDITION REPORTS AND A LOCAL CONTACT STATED THE RUNWAY WAS IN GOOD CONDITION. THEY LANDED AND THE BRAKING ACTION WAS NIL. THE CAPTAIN MANEUVERED THE AIRPLANE TO A DRY PATCH OF DIRT ON THE LEFT SIDE OF THE RUNWAY. WHEN THE MAIN GEAR ROLLED ONTO THE DRY PATCH THE AIRPLANE VEERED SHARPLY TO THE LEFT AND DEPARTED THE RUNWAY. BOTH CREWMEMBERS STATED A GO AROUND WAS NOT POSSIBLE. ACCORDING TO LANDING PERFORMANCE CHARTS, THE MINIMUM LANDING RUNWAY LENGTH WAS 4500 FEET ON A DRY HARD SURFACE RUNWAY. THE ACTUAL RUNWAY LENGTH WAS 3500 FEET.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT-IN-COMMAND'S FAILURE TO PERFORM PROPER PREFLIGHT PLANNING BY NOT COMPUTING THE REQUIRED LANDING RUNWAY LENGTH.

## Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER  
Phase of Operation: LANDING - ROLL

### Findings

1. TERRAIN CONDITION - ICY
2. (C) PREFLIGHT PLANNING/PREPARATION - NOT PERFORMED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER  
Phase of Operation: LANDING - ROLL

## Factual Information

On October 8, 1993, at 1735 Alaska daylight time, a wheel equipped Douglas, C54GDC airplane, N811E, registered to and operated by Brooks Fuel of Fairbanks, Alaska, veered off the left side of the runway after landing at Point Lay, Alaska. The business flight, operating under 14 CFR Part 91, departed Fairbanks, Alaska, with a cargo of unleaded automotive fuel, and the destination was Point Lay. A company flight plan was filed and visual meteorological conditions prevailed. The airplane was substantially damaged and the Pilot-in-Command, Co-Pilot, and the passenger were not injured.

According to the Pilot in Command, there was no runway condition report so they called someone locally at Point Lay and were told that the runway was in good condition. The Captain stated that he applied brakes upon landing and there was some slight braking. As the airplane proceeded down the runway, braking became nil. The Captain attempted to maneuver the airplane toward the left side of the runway onto a visible strip of dirt. The left main gear caught on the dirt and veered the airplane off the left side of the runway.

According to the First Officer they touched down on the end of the runway and the Captain had braking. Shortly there after braking was nil and he said that when the left main gear finally rolled onto the dirt near the left edge of the runway, the airplane made a sharp left turn and left the runway.

Both crewmembers stated that the airplane had progressed far enough down the runway so that a successful go around was impossible.

According to the Alaska Supplement the runway at Point Lay is 3500 feet long and has a field elevation of 20 feet above mean sea level. With the outside air temperature reported as 38 degrees fahrenheit, the density altitude was approximately 19.5 feet. According to the Captain, the landing weight of the airplane was 63,040 pounds.

According to information provided by the Douglas Aircraft Corporation, for a charted gross weight of 63,500 pounds, at sea level, using wing flaps 50, a coefficient of friction of .05 (slippery surface), the landing distance over a 50 foot obstacle listed is 4700 feet. According to the Douglas Aircraft landing performance chart, the minimum effective landing runway length for a dry hard surface was 4500 feet. A distance of 1000 feet greater than the actual landing length of the runway.

Both crewmembers also stated that they had a threshold speed of 94 knots and a touchdown speed of 87 knots. Douglas Aircraft information shows that the airplane should glide at 110 knots and land at 99 knots.

## Pilot Information

<b>Certificate:</b>	Airline Transport; Flight Instructor	<b>Age:</b>	48, Male
<b>Airplane Rating(s):</b>	Multi-engine Land; Multi-engine Sea; Single-engine Land; Single-engine Sea	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane Multi-engine; Airplane Single-engine; Instrument Airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical--w/ waivers/lim.	<b>Last Medical Exam:</b>	08/05/1993
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	20000 hours (Total, all aircraft), 2400 hours (Total, this make and model), 19500 hours (Pilot In Command, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Manufacturer:</b>	DOUGLAS	<b>Registration:</b>	N811E
<b>Model/Series:</b>	C-54GDC C-54GDC	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	No
<b>Airworthiness Certificate:</b>	Provisional; Transport	<b>Serial Number:</b>	36080
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	3
<b>Date/Type of Last Inspection:</b>	10/04/1994, AAIP	<b>Certified Max Gross Wt.:</b>	66700 lbs
<b>Time Since Last Inspection:</b>	20 Hours	<b>Engines:</b>	4 Reciprocating
<b>Airframe Total Time:</b>	28585 Hours	<b>Engine Manufacturer:</b>	P&W
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	R2000-4
<b>Registered Owner:</b>	ROGER W. BROOKS	<b>Rated Power:</b>	1450 hp
<b>Operator:</b>	BROOKS FUEL	<b>Air Carrier Operating Certificate:</b>	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Observation Time:	0000
Distance from Accident Site:	0 Nautical Miles	Direction from Accident Site:	0°
Lowest Cloud Condition:	Unknown / 0 ft agl	Temperature/Dew Point:	3° C
Lowest Ceiling:	Overcast / 3300 ft agl	Visibility	10 Miles
Wind Speed/Gusts, Direction:	10 knots, 130°	Visibility (RVR):	0 ft
Altimeter Setting:		Visibility (RVV):	0 Miles
Precipitation and Obscuration:			
Departure Point:	FAIRBANKS, AK (FAI)	Type of Flight Plan Filed:	Company VFR
Destination:		Type of Clearance:	None
Departure Time:	1500	Type of Airspace:	Airport Advisory Area; Class G

## Airport Information

Airport:	POINT LAY (PIZ)	Runway Surface Type:	Ice
Airport Elevation:	20 ft	Runway Surface Condition:	Ice
Runway Used:	23	IFR Approach:	None
Runway Length/Width:	3500 ft / 100 ft	VFR Approach/Landing:	Full Stop; Traffic Pattern

## Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	

## Administrative Information

Investigator In Charge (IIC):	GEORGE KOBELNYK	Adopted Date:	12/02/1994
Additional Participating Persons:	FSDO 01 ; FAIRBANKS, AK		
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinquiry@ntsb.gov">pubinquiry@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.