



National Transportation Safety Board Aviation Accident Final Report

Location:	Mojave, CA	Accident Number:	WPR09LA108
Date & Time:	02/04/2009, 0852 PST	Registration:	N834TP
Aircraft:	DOUGLAS DC-3/65AR	Aircraft Damage:	Substantial
Defining Event:	Loss of control on ground	Injuries:	2 None
Flight Conducted Under:	Part 91: General Aviation - Instructional		

Analysis

During the takeoff roll, the airplane began to drift to the right. Despite the certified flight instructor's and student's attempts, they were unable to stop the yaw and drift. As the airplane was about to depart the runway, the pilots did not reduce the throttles or apply brakes as they felt that it would be safer to attempt to get airborne. After departing the runway surface, the airplane collided with a series of berms, which sheared off the left landing gear and left engine. The right landing gear collapsed, and the airplane came to rest in a nose down attitude. Post accident examination revealed that the student pilot had inadvertently set the rudder trim to the full right position when he adjusted the rudder pedals during the prestart checks. The rudder trim was in the full right position for the takeoff, and found in the same position upon post accident inspection.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot failed to follow the checklist and set the takeoff trim properly prior to takeoff resulting in a loss of directional control. Contributing to the accident were the certified flight instructor's inadequate supervision and delayed remedial action.

Findings

Aircraft	Rudder tab control system - Incorrect use/operation (Cause) Directional control - Not attained/maintained (Cause)
Personnel issues	Use of checklist - Student pilot (Cause) Monitoring other person - Instructor/check pilot (Factor) Delayed action - Instructor/check pilot (Factor) Use of equip/info - Student pilot (Cause)
Environmental issues	Rough terrain - Contributed to outcome

Factual Information

On February 4, 2009, about 0852 Pacific standard time, a Douglas DC-3/65AR, N834TP, collided with terrain during takeoff at Mojave, California. The National Test Pilot School was operating the airplane under the provisions of 14 Code of Federal Regulations (CFR) Part 91. The certified flight instructor (CFI) and the student pilot were not injured; the airplane sustained substantial damage to the fuselage and wings from impact forces. The local instructional flight was departing. Visual meteorological conditions prevailed, and no flight plan had been filed.

The operator reported that the student pilot was performing the takeoff. During the takeoff roll, the airplane began to drift to the right, and the student applied left rudder to correct for the drift. The CFI advanced the right throttle during the ground roll in an attempt to counteract the right yaw. The tail wheel came off the ground about 80 knots, and the airplane swerved to the right. The CFI applied left rudder in an attempt to stop the yaw and drift. As the airplane was about to depart the runway, the pilots did not reduce the throttles or apply brakes as they felt that it would be safer to attempt to get airborne.

The airplane slowed as it departed the runway surface. It collided with a series of berms, which sheared off the left landing gear and left engine. The right landing gear collapsed, and the airplane came to rest in a nose down attitude.

The operator stated that the student pilot inadvertently set the rudder trim to the full right position when he adjusted the rudder pedals during the prestart checks. The rudder trim was in the full right position for the takeoff, and found in the same position upon post accident inspection.

History of Flight

Prior to flight	Preflight or dispatch event
Takeoff	Loss of control on ground (Defining event) Runway excursion

Flight Instructor Information

Certificate:	Flight Instructor; Commercial	Age:	73, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Right
Other Aircraft Rating(s):	Glider; Helicopter	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane Multi-engine; Airplane Single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 With Waivers/Limitations	Last Medical Exam:	11/25/2008
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	10/13/2008
Flight Time:	18000 hours (Total, all aircraft), 1326 hours (Total, this make and model), 16000 hours (Pilot In Command, all aircraft), 50 hours (Last 90 days, all aircraft), 16 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Student Pilot Information

Certificate:	Foreign	Age:	33, Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Without Waivers/Limitations	Last Medical Exam:	09/30/2008
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	1100 hours (Total, all aircraft), 900 hours (Pilot In Command, all aircraft), 17 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Manufacturer:	DOUGLAS	Registration:	N834TP
Model/Series:	DC-3/65AR	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Experimental	Serial Number:	12590
Landing Gear Type:	Retractable - Tailwheel	Seats:	4
Date/Type of Last Inspection:	01/21/2009, Annual	Certified Max Gross Wt.:	29000 lbs
Time Since Last Inspection:	2 Hours	Engines:	2 Turbo Prop
Airframe Total Time:	17277 Hours	Engine Manufacturer:	Pratt&Whitney
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	PT6A-65AR
Registered Owner:	National Test Pilot School	Rated Power:	1300 hp
Operator:	National Test Pilot School	Air Carrier Operating Certificate:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	MHV, 2798 ft msl	Observation Time:	0850 PST
Distance from Accident Site:		Direction from Accident Site:	
Lowest Cloud Condition:	Few / 12000 ft agl	Temperature/Dew Point:	12 °C / -5 °C
Lowest Ceiling:	None	Visibility	40 Miles
Wind Speed/Gusts, Direction:	3 knots, Variable	Visibility (RVR):	
Altimeter Setting:	30.15 inches Hg	Visibility (RVV):	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Mojave, CA (MHV)	Type of Flight Plan Filed:	None
Destination:	Mojave, CA (MHV)	Type of Clearance:	VFR
Departure Time:	0852 PDT	Type of Airspace:	

Airport Information

Airport:	Mojave (MHV)	Runway Surface Type:	Asphalt; Concrete
Airport Elevation:	2798 ft	Runway Surface Condition:	Dry
Runway Used:	30	IFR Approach:	None
Runway Length/Width:	12500 ft / 200 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	35.058611, -118.150556 (est)

Administrative Information

Investigator In Charge (IIC):	Howard D Plagens	Adopted Date:	05/12/2009
Additional Participating Persons:	Jim Ford; Federal Aviation Administration; Van Nuys, CA		
Publish Date:	05/12/2009		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.